



## Follow-up Service Inspection Report E2332583210323163231

INSPECTION DETAILS			
Date:	2021-03-23	File Number.:	E233258
Responsible Office:	Bangalore	Volume:	3
Inspection Center:	362	CCN:	OBJY2
Product Type:	Electrical Insulation Systems	UL Rep Name:	Ashu Somany
Deliverable Type:	Recognized	UL Rep ID:	12200
Party Site Number:	642803	Subscriber Factory No.:	437522-002
Manufacturer Name:	PRIMA AUTOMATION (INDIA) PVT LTD	Factory Rep Name	Mr. Harshil Modi
Manufacturer Address:	Plot 793 Rakanpur ,Santej Tal. Kalol District Gandhinagar Gujarat	Factory Rep Phone:	+91-2764-286975 to 78
		Factory Rep Email:	harshil.modi@prima- automation.com
Nature of visit:	Initial Production Inspection	Sample Status:	Samples not required
UL Marks Used?	Yes	UL Marks Removed?	No
Variation Notice Issued?	No	Inspection Conducted Remotely?	Yes
Comments After Submission:			

PRODUCT DOCUMENTS/PRODUCTION READY VISIT			
Model	Product	Section	Multiple Listed
PRIMA-155-1	Class F Insulation System	1	No

SAMPLE DOCUMENTS			
If samples are required to be sent to UL, indicate below. If required samples are not sent, explain in the Comments area.			
No Samples			
Additional Comments	IPI carried out today.		

In addition to the requirements specified in the applicable UL Services agreement and Follow-Up Service Procedure, UL further defines responsibilities, duties and requirements for both manufacturers and UL representatives in the document titled "UL Mark Surveillance Requirements" that can be located at [www.ul.com/fus](http://www.ul.com/fus), and in accordance with the applicable terms and conditions of the document at [www.ul.com/responsibilities](http://www.ul.com/responsibilities). Manufacturers without Internet access may obtain the current versions of these documents from their local UL customer service representative or UL field representative.